# ■ TOP COMMUNICATION AND INTERFACE MANUAL

**Published by M2I Corporation** 



**M2I Corporation** 

# **AND WEIGHING INDICATOR Series**

#### **AND WEIGHING INDICATOR Interface**

The following section describes the system configuration and interface between AND Weighing Indicator and TOP by serial RS-232 / RS-485.


## **System Configuration**

This figure shows system configuration to connect AND Weighing indicator to TOP.

Controller	Comm. Unit	Cable	TOP
	•		ТОР
AND Weighing	OP03	Refer to connection	
Indicator	(option module)	diagram RS422/485	
	OP04	Refer to connection	All TOP
	(option module	diagram RS232	

#### **Cable Connection Diagram**


(1) RS-232 connection diagram(AND Weighing Indicator ↔ TOP)



(2) RS-422 connection diagram(AND Weighing Indicator ↔ TOP)

Controller TOP(5Pin Terminal / 15Pin) SDA 1/11 RDA 1 2 SDB 2/12 RDB 3 RDA 3/13 SDA 4 RDB 4/14 SDB 5/15 SG

(3) RS-485 connection diagram(AND Weighing Indicator ↔ TOP)



## AND WEIGHING INDICATOR Setup


CONTROLLER				
No Address				
Address exist	Only for RS422/485			
Address	Only for RS422/485			
Baud Rate	9600 bps			
Data Bit	7 bit			
Stop Bit	1 bit			
Parity Bit	EVEN			

Communication parameters of AND Weighing Indicator can be set using display panel on the front of indicator.

## **TOP Setup**

#### (1) TOP Designer setup

Select Controller type of "AND Weighing Indicator" as shown figure.




#### (2) Serial communication setup in TOP

Communication setup in 'Comm. Setup' Menu are as follows:

- Serial Baud Rate: Same as controller's setup
- Serial Data Bit : Same as controller's setup
- Serial Stop Bit : Same as controller's setup
- Serial Parity Bit : Same as controller's setup
- Serial Signal Level : Same as controller's setup
- Station No. at Communication Diagnosis(0~31): Same as controller's setup

## **Addressing Method of TOP for AND Weighing Indicator**

The address of TOP for AND Weighing Indicator means station number in case of using RS422 / 485 serial interface. Therefore, when TOP is connected to controller with RS-232, address of TOP for AND weighing indicator should be zero (00)



#### **Available Address List**

DEVICE	Command	Read/Write	Address
RW	Data request	R	-
MZ	Zero display	W	-
MT	Tare	W	-
СТ	Clear Tare value	W	-
MG	Display gross value	W	-
MN	Display net value	W	-
Hi	Set upper limit value	W	-
Lo	Set lower limit value	W	-
S0	Set final value	W	-
S1	Set free fall value	W	-
S2	Set preliminary value	W	-
S3	Set zero band	W	